

05/11/25 - cutting out 2 air inlets from bottom cowl - 2h

Category: 6.10 Sam James Cowling

Published: Thursday, 13 November 2025 07:43

Hits: 414

Short work session, continued cutting out air inlets on top cowling. Both are now trimmed to size.



Positioned the rings to verify the fit. Might need a little more trimming but I prefer to be conservative for now until the bottom cowl is also cut.

passenger side



pilot side

