01/05/2020 - Right aileron bracket - 2h

Category: 2.8. Closing skins
Published: Friday, 21 August 2020 04:25
Hits: 811

Started closing work on the right wing today. Just like on the left wings, I preventivly applied the service bulletin on the inner aileron attach brackets.

I had drilled and primed the parts earlier so now it's time to rivet the aileron bracket back on.

I had some issues with 1 rivet that I had to drill out twice. Came out with a bit smaller manuafactured head in the end due to the drilling but it still looks acceptable.

I guess it's one of those things to add to your annual inspection list.

Another shot from the top



After some vacuum cleaning, the right wing is now ready to receive it's bottom skin.

Phoca PDF

01/05/2020 - Right aileron bracket - 2h

Category: 2.8. Closing skins
Published: Friday, 21 August 2020 04:25
Hits: 811



Since I have the experience of the left wing, I hope closing this one will go a bit faster.

Phoca PDF