


Another rivetting session on the forward fuselage.


This time we knocked in the rest of the F705, baggage bulkheads F-722 and F-724s on both sides and most of the joint of aft and center fuselage.



Cindy in action with the 3x gun. She's getting good at timing which makes things a lot easier.



The joint of the forward and aft fuselage are really nice and tight.



view of the belly. Also here very nice joint.

