25/07/2020 - Various tasks - 5h

Category: 2.4. Main Wings
Published: Saturday, 21 November 2020 09:38
Hits: 1225

Today was one of those days that you want to do something on the plane but don't actually have a plan what to do next. Most of the time I have tons of things preplanned but now and then it happens.

I took out my newly drilled elevator horns (after welding and redrilling) and deburred them.



The hole looks really nice and clean after deburring. Just what you want on a control surface part.

As part of the work today, I scuffed, degreased and put some new white paint over the exposed part using a rattle can.

Worked also on the other wing inner ribs, installing nutplates.

Finally got the two triangular parts out of the stock which will

Phoca PDF

25/07/2020 - Various tasks - 5h

Category: 2.4. Main Wings
Published: Saturday, 21 November 2020 09:38
Hits: 1225

reinforce the back of the wingtip and deburred and cleaned the edges?



Phoca PDF